

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/29/2016
Submitted Date:
11/29/2016
Document Number:
680301421

FIELD INSPECTION FORM

Loc ID 312290 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10330
Name of Operator: INVESTMENT EQUIPMENT LLC
Address: 412 W PLATTE AVE
City: FT MORGAN State: CO Zip: 80701

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Rebol, Dave		daverebol@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221073	WELL	PR	04/05/2016	GW	075-09199	CEDAR CREEK RANCH 1	PA

General Comment:

FIR on P&A Inspection correcting error on Doc# 680301421. Emergency contact no. comment placed in corrective action tab. No corrective actions are required. P&A Satisfactory - Operator/Contractor will contact F.I. Schure when surface pipe is cut off (4') below surface and cap welded on for backfill. Surface equipment needs to be removed - Operator/Contractor will contact Schure upon completion of equipment removal/site clean-up-prepared for reclamation inspection. This FIR is related to P&A results only - any corrective actions from previous FIR's remain in effect.

Inspected Facilities

Facility ID: 221073 Type: WELL API Number: 075-09199 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: FIR submitted to correct error on Doc# 680301412 - No corrective actions required - See comments pg. 1 for details - P&A Satisfactory

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
P&A SATISFACTORY - Please contact Field Inspector Schure when site is ready for surface inspection for well cut off (4') below surface with cap welding on ready for backfill and surface equipment is removed. Contact COGCC Reclamation Group for Final Reclamation and COGCC Environmental Group for pit closure when appropriate.	schureky	11/29/2016