

Caerus Site Inspection, Well API# 045-07492

November 23, 2016



Excavation into weathered bedrock looking north



Steep unstable slope above excavation