

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2016

Submitted Date:

11/29/2016

Document Number:

681901779**FIELD INSPECTION FORM**
 Loc ID 318254 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name   | Phone          | Email                 | Comment                         |
|----------------|----------------|-----------------------|---------------------------------|
| Fritzler, Gene | (970) 867-9388 | gfritzler@bresnan.net | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                 | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------------|-------------|
| 240980      | WELL | PR     | 07/07/1997  | GW         | 123-08768 | B C HOPKINS 31-19 (1-67)<br>3 | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | WELLHEAD     |       |  |
| Comment:           | SATISFACTORY |       |  |
| Corrective Action: |              | Date: |  |

Emergency Contact Number:

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Comment:           | SATISFACTORY | Date: |  |
| Corrective Action: |              |       |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                    |              |       |                 |
|--------------------|--------------|-------|-----------------|
| Type: Pump Jack    | # 1          |       | corrective date |
| Comment:           | SATISFACTORY |       |                 |
| Corrective Action: |              | Date: |                 |

**Tanks and Berms:**

| Contents           | #              | Capacity | Type | Tanak ID | SE GPS |
|--------------------|----------------|----------|------|----------|--------|
|                    |                |          |      |          |        |
| Comment:           | REMOTE BATTERY |          |      |          |        |
| Corrective Action: |                | Date:    |      |          |        |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |        |                                  |      |             |           |         |    |               |    |
|----------------------|--------|----------------------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 240980 | Type:                            | WELL | API Number: | 123-08768 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |                                  |      |             |           |         |    |               |    |
| Comment:             |        | PR                               |      |             |           |         |    |               |    |
| Corrective Action:   |        |                                  |      |             |           | Date:   |    |               |    |
| BradenHead           |        |                                  |      |             |           |         |    |               |    |
| Comment:             |        | Bradenhead is plumed to surface. |      |             |           |         |    |               |    |
| Corrective Action:   |        |                                  |      |             |           | Date:   |    |               |    |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established In

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT