

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/28/2016

Submitted Date:

11/30/2016

Document Number:

666802766**FIELD INSPECTION FORM**

Loc ID 334800 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211584	WELL	PR	10/01/2003	GW	045-07345	WAGSTROM 8-13 (M8E)	PR
258224	WELL	PR	12/09/2000	GW	045-07621	WAGSTROM 8-13A (M8E)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	0				,	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tanak ID		SE GPS		
CONDENSATE		1	300 BBLS	STEEL AST				39.457332,-107.697231		
Comment:										

Corrective Action:		Date:		
Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected FacilitiesFacility ID: 211584 Type: WELL API Number: 045-07345 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 258224 Type: WELL API Number: 045-07621 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Ditches	Pass			
Ditches	Pass					
		Gravel	Pass			

Comment: Rill erosion forming on south side of location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT