

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2016

Submitted Date:

11/30/2016

Document Number:

685501489**FIELD INSPECTION FORM**
 Loc ID 306550 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | COGCCinspections@anadarko.com | All Inspections |
| REDDY, LUKE | | Luke.Reddy@anadarko.com | ALL INSPECTIONS |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 289675 | WELL | PR | 10/01/2014 | GW | 123-24895 | Steward USX XX 07-15 | PR |

General Comment:

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | ROD IRON FENCE SE CORNER N40.06028 W-104.70427 | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----------------|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | NO AIRS NUMBER | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-------------------|-------|--|
| Flaring: | | | |
| Type | Ignitor/Combustor | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------------------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 289675 | Type: | WELL | API Number: | 123-24895 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Comment: | | BRADENHEAD PLUMBED TO SURFACE | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|----------|------------|
| INTERMITTER CONTROLLER ON WELLHEAD THIS WELL GOES TO THE GOODIN TANK BATTERY | montoyaj | 11/30/2016 |