

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2016

Submitted Date:

12/02/2016

Document Number:

675203657**FIELD INSPECTION FORM**
 Loc ID 311559 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Terra, Energy		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210788	WELL	PR	09/16/1987	GW	045-06546	MITCHELL W-27-3	PR
210932	WELL	PR	10/24/2002	GW	045-06690	MITCHELL GV 75-3	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	NO	<input type="text"/>
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	
	Date:	<input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	
	Date:	<input type="text"/>

Inspected Facilities									
Facility ID:	<u>210788</u>	Type:	<u>WELL</u>	API Number:	<u>045-06546</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>210932</u>	Type:	<u>WELL</u>	API Number:	<u>045-06690</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT