

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/28/2016

Submitted Date:

11/28/2016

Document Number:

674004627**FIELD INSPECTION FORM**

Loc ID 336160 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|-------------------------------|---------------------------------|
| , Inspections | | COGCCinspections@Anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 251270 | WELL | PR | 05/02/1999 | GW | 123-19073 | HSR-CAMP 8-24 | PR |
| 414287 | WELL | PR | 10/13/2011 | GW | 123-30716 | CAMP 41-24 | PR |
| 414292 | WELL | PR | 10/13/2011 | OW | 123-30719 | CAMP 24-24 | PR |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|--------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Pipe | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Barb Wire | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|-----|-------|-----------------|
| | | | corrective date |
| Type: Plunger Lift | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 2 | | |

| | | | |
|-------------------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|----------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|---------|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | 210 Bbl | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|------------------------------|---------------------|---------------------|-------------|-----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | Shared with crude oil tanks. | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | | 40.208780,-104.826650 |
| Comment: | | | | | |
| Corrective Action: | | | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | |

Flaring:

| | | |
|------|-------------------|--|
| Type | Ignitor/Combustor | |
|------|-------------------|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 251270 Type: WELL API Number: 123-19073 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**BradenHead**Comment: Corrective Action: Date: _____Facility ID: 414287 Type: WELL API Number: 123-30716 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**BradenHead**Comment: Corrective Action: Date: _____Facility ID: 414292 Type: WELL API Number: 123-30719 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**BradenHead**Comment: Corrective Action: Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Battery shut in.

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IMPROVED PASTURE

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IMPROVED PASTURE _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|-------------------------------------|----------|------------|
| Routine inspection. | carlilec | 11/28/2016 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 674004627 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4013751 |