

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/28/2016

Submitted Date:

11/28/2016

Document Number:

681901765**FIELD INSPECTION FORM**
 Loc ID 336486 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num: _____
Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Findings:**24 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | COGCCinspections@anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 288069 | WELL | PR | 05/23/2010 | GW | 123-24499 | WELD 2-2 | PR |
| 288070 | WELL | PR | 11/02/2010 | GW | 123-24498 | WELD 7-2 | PR |
| 288203 | WELL | PR | 04/30/2010 | OW | 123-24551 | WELD 27-2 | PR |
| 288204 | WELL | PR | 04/29/2010 | GW | 123-24550 | WELD 21-2 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: SATISFACTORY

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------------------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Barbed wire topped chain link | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Barbed wire topped chain link | | |
| Corrective Action: | | Date: | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Barbed wire topped chain link | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Barbed wire topped chain link | | |
| Corrective Action: | | Date: | |

| | | | |
|-------------------------------|--------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Emission Control Device | # 2 | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |

| | | |
|-----------------------------------|-----|-------|
| Comment: SATISFACTORY | | Date: |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 4 | |
| Comment: SATISFACTORY | | Date: |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 6 | |
| Comment: SATISFACTORY | | Date: |
| Corrective Action: | | Date: |
| Type: Gas Meter Run | # 1 | |
| Comment: SATISFACTORY | | Date: |
| Corrective Action: | | Date: |
| Type: VRU | # 1 | |
| Comment: SATISFACTORY | | Date: |
| Corrective Action: | | Date: |
| Type: Plunger Lift | # 5 | |
| Comment: SATISFACTORY | | Date: |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 210 BBL |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 3 | OTHER | STEEL AST | | 40.172680,-104.966110 |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 315BBL |

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Inspected FacilitiesFacility ID: 288069 Type: WELL API Number: 123-24499 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: Bradenhead is plumed to surface.

Corrective Action:

Date: _____

Facility ID: 288070 Type: WELL API Number: 123-24498 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: Bradenhead is plumed to surface.

Corrective Action:

Date: _____

Facility ID: 288203 Type: WELL API Number: 123-24551 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: Bradenhead is plumed to surface.

Corrective Action:

Date: _____

Facility ID: 288204 Type: WELL API Number: 123-24550 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: Bradenhead is plumed to surface.

Corrective Action:

Date: _____

| Environmental | |
|------------------------------------|--|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): YES | |
| Comment: | |
| Pilot: ON | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-CroplandTop soil replaced Pass Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 681901765 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4018077 |