

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2016

Submitted Date:

11/29/2016

Document Number:

666802754**FIELD INSPECTION FORM**

Loc ID 335120	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>VANGUARD OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>				Findings: 16 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291271	WELL	PR	11/20/2007	GW	045-14322	GEISKE 43C-26-692	PR
291273	WELL	PR	11/21/2007	GW	045-14323	GEISKE 42A-26-692	PR
291308	WELL	PR	05/09/2013	GW	045-14330	GEISKE 32B-26-692	PR
291314	WELL	PR	11/24/2007	GW	045-14325	GEISKE 32D-26-692	PR
297963	WELL	PR	05/21/2009	GW	045-17004	GEISKE 41B-26-692	PR
297964	WELL	PR	05/21/2009	GW	045-17005	GEISKE 41A-26-692	PR
297965	WELL	PR	05/15/2009	GW	045-17006	GEISKE 42C-26-692	PR
297966	WELL	PR	05/15/2009	GW	045-17007	GEISKE 42D-26-692	PR
297967	WELL	PR	05/15/2009	GW	045-17008	GEISKE 43D-26-692	PR
297968	WELL	PR	05/18/2009	GW	045-17009	GEISKE 32C-26-692	PR
297969	WELL	PR	05/18/2009	GW	045-17010	GEISKE 42B-26-692	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1583-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Gas Meter Run	# 0				
Comment:					
Corrective Action:					
Type: Horizontal Heated Separator	# 11				
Comment:					
Corrective Action:					
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:					
Type: Pig Station	# 1				
Comment:					
Corrective Action:					
Type: Ancillary equipment	# 3				
Comment:		Chemical units at wellhead			
Corrective Action:					
Type: Plunger Lift	# 11				
Comment:					
Corrective Action:					

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		39.499822,-107.630338
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLS	STEEL AST		39.499806,-107.630399	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	291271	Type:	WELL	API Number: 045-14322	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	291273	Type:	WELL	API Number: 045-14323	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	291308	Type:	WELL	API Number: 045-14330	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	291314	Type:	WELL	API Number: 045-14325	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	297963	Type:	WELL	API Number: 045-17004	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	297964	Type:	WELL	API Number: 045-17005	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	297965	Type:	WELL	API Number: 045-17006	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	297966	Type:	WELL	API Number: 045-17007	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:

Facility ID:	297967	Type:	WELL	API Number:	045-17008	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	297968	Type:	WELL	API Number:	045-17009	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	297969	Type:	WELL	API Number:	045-17010	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Gravel	Pass			
Culverts	Pass					
		Ditches	Pass			
Gravel	Pass					
Ditches	Pass					
		Check Dams	Pass			
		Culverts	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802754	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4019127