



photo 1: Facing northwest toward the location.



photo 2: East side of the location facing west.



photo 3: View of groundcover at the south side of the location. The dried up vegetation is Cheat grass (list c noxious weed).



photo 4: North side of the location facing south.



photo 5: Northwest side of the location facing southeast.



photo 6: Facing toward the west side of the location.



photo 7: West side of the location facing northwest.



photo 8: Facing east toward the surrounding undisturbed reference area.