



**photo 1:** Facing toward the beginning of the access road.



**photo 2:** Facing west along the access road. The access road has not been reclaimed and there is noxious weed infestation along the road.





**photo 3:** There is Diffuse and Spotted knapweed (List B noxious weeds) growing along the access road and at the location.



**photo 4:** Facing north toward the location.





**photo 5:** An electrical utility remains at the southeast side of the location.



**photo 6:** An electrical utility remains at the southeast side of the location.





**photo 7:** North side of the location facing south.



**photo 8:** North side of the location facing southwest. The Russian olive tree (list B noxious weed) is still present.