

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/17/2016
Submitted Date:
11/17/2016
Document Number:
680000726

FIELD INSPECTION FORM

Loc ID 433513 Inspector Name: QUINT, CRAIG On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 61250
Name of Operator: MULL DRILLING COMPANY INC
Address: 1700 N WATERFRONT PKWY B#1200
City: WICHITA State: KS Zip: 67206-

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|------------------|---------------------------|--|
| Smalley, Carl | 719-767-8805 off | csmalley@mulldrilling.com | 719-342-1812 cell |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 433519 | WELL | PR | 09/13/2013 | OW | 017-07755 | APC-BAUGHMAN UNIT 1-35 | PR |

General Comment:

Location

| | | | |
|--------------------|-----------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Short gravel road through pasture | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | Lease sign by tanks | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Stickers | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by unit | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal signs by tanks | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|-------|
| Comment: | | | |
| Corrective Action: | | Date: | _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|-------------------------------------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Steel panels around unit crank arms | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Location fenced with wire | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Prime Mover | # 1 | | |
| Comment: | Elec motor | | |
| Corrective Action: | | Date: | |

| | | | |
|---|-----|-------|--|
| Type: Pump Jack | # 1 | | |
| Comment: 456 C&W | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 5 | | |
| Comment: Elec control panel, 2-chemical tanks w/BMP, cathodic rectifier, propane tank | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heater Treater | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------------------------|---|----------|----------------|---------|-----------------------|
| PRODUCED WATER | 1 | 300 BBLs | FIBERGLASS AST | | 38.616840,-102.437260 |
| Comment: 280 bbl water tank | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 38.616840,-102.437260 |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Location Construction

Location ID: 433519 CDP: _____

Comment:

Corrective Action: Date: _____

Form 2A COAs:

Comment: No issues observed

Corrective Action: Date: _____

Wildlife BMPs:

Comment:

Corrective Action: Date: _____

Comment:

Corrective Action: Date: _____

On Site Inspection (305):

Surface Owner Contact Information:
 Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:
 Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
 Request LGD Attendance: _____

LGD Contact Information:
 Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 433519 Type: WELL API Number: 017-07755 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | |
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 680000726 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017277 |