

Final Reclamation Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 1. Photo taken of well sign for API #123-14163 confirming well release of API #123-37799 on an active location.

Final Reclamation Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 2. Photo taken of well sign for API #123-39223 confirming well release of API #123-37799 on an active location.

Final Reclamation Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 3. Photo taken of well sign for API #123-37798 confirming well release of API #123-37799 on an active location.

Final Reclamation Inspection



Photo 4. Photo taken of well sign for API #123-37800 confirming well release of API #123-37799 on an active location.