



Photo#1: Overview of Annex Location from Original Pad to South; houses Nine PR Wells.



Photo#2: View of Annex Location to NW.

Inspection Photos: Laramie Energy Cascade Creek Loc#335643

November 16, 2016





Photo#3: View of Original Pad, located Above Annex Location, Which houses Two PR Wells.

Inspection Photos: Laramie Energy Cascade Creek Loc#335643

November 16, 2016



Photo#4: Fill Slopes consist of Rocky/ shale Material with little to No Vegetation.

Inspection Photos: Laramie Energy Cascade Creek Loc#335643

November 16, 2016





Photo#5: Aerial Image of Location that has not had Areas no longer needed for Use or Production Reclaimed.

Inspection Photos: Laramie Energy Cascade Creek Loc#335643

November 16, 2016