



**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Emergency Contact Number:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
|                    |     |       | corrective date |
| Type: Plunger Lift | # 5 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

**Tanks and Berms:**

| Contents           | #                            | Capacity | Type                | Tank ID | SE GPS |
|--------------------|------------------------------|----------|---------------------|---------|--------|
|                    |                              |          | CENTRALIZED BATTERY |         | ,      |
| Comment:           | Shared with API 05-123-40860 |          |                     |         |        |
| Corrective Action: |                              |          |                     | Date:   |        |

**Paint**

|                  |  |  |  |
|------------------|--|--|--|
| Condition        |  |  |  |
| Other (Content)  |  |  |  |
| Other (Capacity) |  |  |  |
| Other (Type)     |  |  |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     | Date:               |             |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities                   |            |                       |            |                  |
|--|------------|-----------------------|------------|------------------|
| Facility ID: 440486                    | Type: WELL | API Number: 123-40860 | Status: DG | Insp. Status: DG |
| <b>Producing Well</b>                  |            |                       |            |                  |
| Comment: PR                            |            |                       |            |                  |
| Corrective Action:                     |            |                       | Date:      |                  |
| <b>BradenHead</b>                      |            |                       |            |                  |
| Comment: Bradenhead plubed to surface. |            |                       |            |                  |
| Corrective Action:                     |            |                       | Date:      |                  |
| Facility ID: 440512                    | Type: WELL | API Number: 123-40880 | Status: DG | Insp. Status: DG |
| <b>Producing Well</b>                  |            |                       |            |                  |
| Comment: PR                            |            |                       |            |                  |
| Corrective Action:                     |            |                       | Date:      |                  |
| <b>BradenHead</b>                      |            |                       |            |                  |
| Comment: Bradenhead plubed to surface. |            |                       |            |                  |
| Corrective Action:                     |            |                       | Date:      |                  |
| Facility ID: 440513                    | Type: WELL | API Number: 123-40881 | Status: DG | Insp. Status: DG |
| <b>Producing Well</b>                  |            |                       |            |                  |
| Comment: PR                            |            |                       |            |                  |
| Corrective Action:                     |            |                       | Date:      |                  |
| <b>BradenHead</b>                      |            |                       |            |                  |
| Comment: Bradenhead plubed to surface. |            |                       |            |                  |
| Corrective Action:                     |            |                       | Date:      |                  |
| Facility ID: 440514                    | Type: WELL | API Number: 123-40882 | Status: DG | Insp. Status: DG |
| <b>Producing Well</b>                  |            |                       |            |                  |
| Comment: PR                            |            |                       |            |                  |
| Corrective Action:                     |            |                       | Date:      |                  |
| <b>BradenHead</b>                      |            |                       |            |                  |
| Comment: Bradenhead plubed to surface. |            |                       |            |                  |
| Corrective Action:                     |            |                       | Date:      |                  |
| Facility ID: 440516                    | Type: WELL | API Number: 123-40884 | Status: DG | Insp. Status: DG |
| <b>Producing Well</b>                  |            |                       |            |                  |
| Comment: PR                            |            |                       |            |                  |
| Corrective Action:                     |            |                       | Date:      |                  |

**BradenHead**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment                             | User     | Date       |
|-------------------------------------|----------|------------|
| <a href="#">Routine inspection.</a> | carlilec | 12/09/2016 |