

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/08/2016

Submitted Date:

12/09/2016

Document Number:

666802783**FIELD INSPECTION FORM**
 Loc ID 335006 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Janicek, Jake		JJanicek@caerusoilandgas.com	
McKee, Michael		MMckee@caerusoilandgas.com	EHS
Elsener, Garrett		garrett@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292139	WELL	PR	06/11/2009	GW	045-14604	SAVAGE 8-11A	PR
292744	WELL	PR	07/01/2013	GW	045-14759	SAVAGE 8-21C	PR
292745	WELL	PR	12/07/2008	GW	045-14758	SAVAGE 8-11D	PR
292746	WELL	PR	11/25/2008	GW	045-14757	SAVAGE 8-21D	PR
292747	WELL	PR	12/01/2014	GW	045-14756	SAVAGE 8-21B	PR
292748	WELL	PR	06/21/2009	OW	045-14755	SAVAGE 8-21A	PR
292749	WELL	PR	11/07/2008	GW	045-14754	SAVAGE 8-12D	PR
292750	WELL	PR	11/01/2008	GW	045-14753	SAVAGE 8-12C	PR
292751	WELL	PR	12/09/2008	GW	045-14752	SAVAGE 8-11C	PR
292752	WELL	PR	06/30/2009	GW	045-14751	SAVAGE 8-11B	PR
292753	WELL	PR	11/19/2008	GW	045-14750	SAVAGE 8-12B	PR
292754	WELL	PR	11/17/2008	GW	045-14749	SAVAGE 8-12A	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1725-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 12		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:	At separators				
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	500gal
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	300 BBLs	STEEL AST		39.456373,-107.915841	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	292139	Type:	WELL	API Number: 045-14604 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	292744	Type:	WELL	API Number: 045-14759 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	292745	Type:	WELL	API Number: 045-14758 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	292746	Type:	WELL	API Number: 045-14757 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	292747	Type:	WELL	API Number: 045-14756 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	292748	Type:	WELL	API Number: 045-14755 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	292749	Type:	WELL	API Number: 045-14754 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	292750	Type:	WELL	API Number: 045-14753 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:		Date:		

Facility ID:	292751	Type:	WELL	API Number:	045-14752	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	292752	Type:	WELL	API Number:	045-14751	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	292753	Type:	WELL	API Number:	045-14750	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	292754	Type:	WELL	API Number:	045-14749	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Gravel	Pass			
		Culverts	Pass			
Berms	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT