

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/13/2016

Submitted Date:

12/14/2016

Document Number:

675203670**FIELD INSPECTION FORM**

Loc ID 334569 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Terra, Energy		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257876	WELL	PR	01/05/2007	OW	045-07609	KNIGHT PA 41-4	PR
285148	WELL	PR	06/14/2006	GW	045-12381	KNIGHT PA 332-4	PR
285754	WELL	PR	07/19/2006	GW	045-12554	KNIGHT PA 42-4	PR
285755	WELL	PR	07/19/2006	GW	045-12548	KNIGHT PA 531-4	PR
285756	WELL	PR	07/19/2006	GW	045-12549	KNIGHT PA 341-4	PR
285758	WELL	PR	07/19/2006	GW	045-12547	KNIGHT PA 441-4	PR
285760	WELL	PR	07/19/2006	GW	045-12546	KNIGHT PA 431-4	PR
285762	WELL	PR	07/19/2006	GW	045-12545	KNIGHT PA 32-4	PR
285764	WELL	PR	07/19/2006	GW	045-12550	KNIGHT PA 432-4	PR
285766	WELL	PR	04/11/2007	GW	045-12551	KNIGHT PA 532-4	PR
285768	WELL	PR	07/19/2006	GW	045-12552	KNIGHT PA 342-4	PR
285771	WELL	PR	04/11/2007	GW	045-12553	KNIGHT PA 442-4	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type SEPARATOR

Comment: Corrective Action: Date: 

Type WELLHEAD

Comment: Corrective Action: Date: 

Type TANK BATTERY

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

**Paint**

Condition Adequate

Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Metal	Adequate		Walls Sufficent		Base Sufficent		Adequate			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID		SE GPS		
PRODUCED WATER		2	300 BBLS	STEEL AST				,		
Comment:										

Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	<u>257876</u>	Type:	<u>WELL</u>	API Number:	<u>045-07609</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285148</u>	Type:	<u>WELL</u>	API Number:	<u>045-12381</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285754</u>	Type:	<u>WELL</u>	API Number:	<u>045-12554</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285755</u>	Type:	<u>WELL</u>	API Number:	<u>045-12548</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285756</u>	Type:	<u>WELL</u>	API Number:	<u>045-12549</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285758</u>	Type:	<u>WELL</u>	API Number:	<u>045-12547</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285760</u>	Type:	<u>WELL</u>	API Number:	<u>045-12546</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285762</u>	Type:	<u>WELL</u>	API Number:	<u>045-12545</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285764</u>	Type:	<u>WELL</u>	API Number:	<u>045-12550</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285766</u>	Type:	<u>WELL</u>	API Number:	<u>045-12551</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285768</u>	Type:	<u>WELL</u>	API Number:	<u>045-12552</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285771</u>	Type:	<u>WELL</u>	API Number:	<u>045-12553</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT