

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2016

Submitted Date:

12/14/2016

Document Number:

675203671**FIELD INSPECTION FORM**
 Loc ID 334598 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Terra, Energy		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282497	WELL	PR	01/10/2006	GW	045-11774	KNIGHT PA 411-3	PR
282951	WELL	PR	01/31/2006	GW	045-11880	KNIGHT PA 312-3	PR
282952	WELL	PR	01/31/2006	GW	045-11879	KNIGHT PA 412-3	PR
282953	WELL	PR	02/14/2013	GW	045-11878	KNIGHT PA 512-3	PR
282954	WELL	PR	07/16/2012	GW	045-11877	KNIGHT PA 511-3	PR
282955	WELL	PR	01/31/2006	GW	045-11876	KNIGHT PA 12-3	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities				
Facility ID: <u>282497</u>	Type: <u>WELL</u>	API Number: <u>045-11774</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282951</u>	Type: <u>WELL</u>	API Number: <u>045-11880</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282952</u>	Type: <u>WELL</u>	API Number: <u>045-11879</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282953</u>	Type: <u>WELL</u>	API Number: <u>045-11878</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282954</u>	Type: <u>WELL</u>	API Number: <u>045-11877</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282955</u>	Type: <u>WELL</u>	API Number: <u>045-11876</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Retention Ponds	Pass					
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT