

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/09/2016

Submitted Date:

12/14/2016

Document Number:

666802795

FIELD INSPECTION FORM

Loc ID 335160 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211107	WELL	PR	11/07/1994	GW	045-06866	CLOUGH RMV 4-16	PR
279769	WELL	PR	04/27/2007	GW	045-11084	CLOUGH RWF 343-16	PR
279896	WELL	PR	04/27/2007	GW	045-11095	CLOUGH RWF 433-16	PR
279897	WELL	PR	04/27/2007	GW	045-11096	CLOUGH RMV 164-16	PR
279899	WELL	PR	04/27/2007	GW	045-11097	CLOUGH RWF 431-21	PR
279901	WELL	PR	04/27/2007	GW	045-11098	CLOUGH RWF 534-16	PR
279903	WELL	PR	07/31/2008	GW	045-11099	CLOUGH RWF 33-16	PR
279904	WELL	PR	04/27/2007	GW	045-11100	CLOUGH RMV 151-21	PR
279907	WELL	PR	04/27/2007	GW	045-11101	CLOUGH RWF 434-16	PR
279908	WELL	PR	08/18/2008	GW	045-11103	CLOUGH RWF 541-21	PR
279909	WELL	PR	07/31/2008	GW	045-11102	CLOUGH RWF 334-16	PR
279910	WELL	PR	04/27/2007	GW	045-11104	CLOUGH RWF 333-16	PR
279911	WELL	PR	04/27/2007	GW	045-11105	CLOUGH RWF 344-16	PR
279912	WELL	PR	04/27/2007	GW	045-11106	CLOUGH RWF 543-16	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	AIRS ID 045-1880-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 0		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	
Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		39.519802,-107.889431
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	200 BBLs	STEEL AST		
Comment: Centralized battery					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	211107	Type:	WELL	API Number:	045-06866	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279769	Type:	WELL	API Number:	045-11084	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279896	Type:	WELL	API Number:	045-11095	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279897	Type:	WELL	API Number:	045-11096	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279899	Type:	WELL	API Number:	045-11097	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279901	Type:	WELL	API Number:	045-11098	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279903	Type:	WELL	API Number:	045-11099	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279904	Type:	WELL	API Number:	045-11100	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: <u>279907</u>	Type: <u>WELL</u>	API Number: <u>045-11101</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:				Date:
Facility ID: <u>279908</u>	Type: <u>WELL</u>	API Number: <u>045-11103</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:				Date:
Facility ID: <u>279909</u>	Type: <u>WELL</u>	API Number: <u>045-11102</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:				Date:
Facility ID: <u>279910</u>	Type: <u>WELL</u>	API Number: <u>045-11104</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:				Date:
Facility ID: <u>279911</u>	Type: <u>WELL</u>	API Number: <u>045-11105</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:				Date:
Facility ID: <u>279912</u>	Type: <u>WELL</u>	API Number: <u>045-11106</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:				Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening	Pass					
		Ditches	Pass			
Ditches	Pass					
		Gravel	Pass			
Drains	Pass					
		Culverts	Pass			
Seeding	Pass					
Check Dams	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT