



photo 1: Facing north at the beginning of the access road. A cattle guard remains at this point.



photo 2: Facing north along the access road.



photo 3: There is little to no vegetation establishment in areas along the access road.



photo 4: Facing north toward the location.



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 9: View of groundcover.



photo 10: A shovel (3 ft.) indicates growth of weeds (Russian thistle, Kochia).



photo 11: Facing west toward the surrounding undisturbed pasture.