



photo 1: Facing west toward the disturbed area off the county road.



photo 2: Facing southwest toward the disturbed area off the county road.



photo 3: Facing northwest along the access road.



photo 4: The fence around the location is down in the southeast corner.



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 9: View of groundcover.




photo 10: Facing west toward the surrounding undisturbed pasture.