

Final Reclamation & Stormwater Inspection

12/13/2016

Operator: Petro-Canada #72085

Location ID: 375675

Adams County, CO

NESE Section 23 T3S R59W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



2016/12/13 10:14

N39.774695 W103.946657

Figure 2: Photo taken from the well location, facing south. Photo shows well location has not achieved uniform vegetative cover, or that reclamation work has not been conducted as required by inspection doc. #682500940



2016/12/13 10:14

N39.774682 W103.946738

Figure 3: Photo taken from the well location, facing east. Photo shows well location has not achieved uniform vegetative cover, or that reclamation work has not been conducted as required by inspection doc. #682500940



2016/12/13 10:23

N39.774325 W103.946785

Figure 4: Photo taken down slope, south of the well location. Photo shows unvegetated areas experiencing degradation due to stormwater.



2016/12/13 10:16

N39.773790 W103.946343

Figure 5: Photo taken from within the fenced remediation area. Photo shows reclamation work has not been conducted as required by inspection doc. #682500940