

Final Reclamation & Stormwater Inspection

12/13/2016

Operator: Petro-Canada #72085

Location ID: 376781

Adams County, CO

NENW Section 24 T3S R59W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo taken from the west end of the location, facing south. Photo shows road has not been re-contoured. Refer to inspection doc. 682500936 for more details



Figure 2: Photo taken from the west end near the battery/pit facility of the location, facing north. Photo shows road has not been re-contoured, and portions of battery/pit remain unvegetated. Refer to inspection doc. 682500936 for more details



2016/12/13 10:47

N39.780805 W103.938338

Figure 3: Photo taken from the west end of the location, facing east. Photo shows road has not been re-contoured. Refer to inspection doc. 682500936 for more details



2016/12/13 10:49

N39.781078 W103.936800

Figure 4: Photo taken from the well. Photo shows well location has not achieved uniform, desirable perennial vegetative cover. Refer to inspection doc. 682500936 for more details



Figure 5: Photo taken from the well location, facing northwest. Photo shows well location has not been re-contoured, and slopes are experiencing erosion. Refer to inspection doc. 682500936 for more details