

Location Overview



Google Earth aerial photo taken 9/7/2013 of the LC22-02 pad location. Total area of 8.6 acres was mapped using a Trimble Juno 3B handheld device. Perimeter of location was mapped and highlighted in red.

Construction and Stormwater Inspection



Photo 1. Photo taken from the northeast location, facing West. Temporary BMP, surface roughening, installed around perimeter of location.

Construction and Stormwater Inspection



Photo 2. Photo taken from the northeast location, facing South. Temporary BMP, surface roughening, installed around perimeter of location.

Construction and Stormwater Inspection



Photo 3. Photo taken from the southeast location, facing West. Temporary BMP, surface roughening, installed around perimeter of location.

Construction and Stormwater Inspection



Photo 4. Photo taken from the southwest location, facing North. Temporary BMP, surface roughening, installed around perimeter of location.

Construction and Stormwater Inspection



Photo 5. Photo taken from the southwest location, facing East, towards to topsoil stockpile.