

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2016

Submitted Date:

12/14/2016

Document Number:

666802803**FIELD INSPECTION FORM**
 Loc ID 334797 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------|---------|
| Contact, General | | cogcc.inspections@encana.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 211594 | WELL | PR | 10/01/2003 | GW | 045-07355 | COUEY 17-3 | PR |
| 275015 | WELL | PR | 05/11/2005 | GW | 045-13447 | COUEY 17-6A1 (C17E) | PR |
| 275017 | WELL | PR | 05/11/2005 | GW | 045-13448 | COUEY 17-3A (C17E) | PR |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | BATTERY | | |
| Comment: | AIRS ID 045-0941-001 | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| Type | # | Comment | Corrective Action | Date | corrective date |
|-----------------------------------|-----|--------------------|-------------------|-------|-----------------|
| Type: Ancillary equipment | # 0 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |
| Type: Plunger Lift | # 3 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 2 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 2 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |
| Type: Pig Station | # 0 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------|---------|--------|
| PRODUCED WATER | 0 | | | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|--|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 2 | 300 BBLs | STEEL AST | | 39.452071,-107.693836 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 211594 Type: WELL API Number: 045-07355 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 275015 Type: WELL API Number: 045-13447 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 275017 Type: WELL API Number: 045-13448 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | | | | | |
| Ditches | Pass | | | | | |
| | | Ditches | Pass | | | |
| Gravel | Pass | | | | | |
| Sediment Traps | Pass | | | | | |
| Seeding | Pass | | | | | |
| | | Culverts | Pass | | | |
| | | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT