

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/03/2016
Submitted Date:
12/15/2016
Document Number:
685100102

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: NEIDEL, KRIS On-Site Inspection
313101 _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10323
Name of Operator: ENTEK GRB LLC
Address: 165 SOUTH UNION #366
City: LAKEWOOD State: CO Zip: 80228

Findings:

1 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
parsons, Kim		kparsons@entekenergy.com	
stocks, kristen	303-282-4633	KStocks@entekenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257246	WELL	PR	09/22/2005	GW	081-06973	ROBIDOUX 23-13	EI

General Comment:

Environmental Staff inspected location on 11/3/2016. The well was SI at time of inspection. There is a treater inside the tank battery berm and a pipe riser on the north side of location. Tank battery has 3-400 Above ground tanks with an earth berm and a gas meter. Well is on a top drive pump. Location is free of any vegetation. Signs present on location. NO pictures are included in this inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		40.991904,-107.329569
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected Facilities

Facility ID: 257246 Type: WELL API Number: 081-06973 Status: PR Insp. Status: EI