

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/06/2016
Submitted Date:
12/15/2016
Document Number:
685200234

FIELD INSPECTION FORM

Loc ID 326580 Inspector Name: LABOWSKIE, STEVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre		sabre.beebe@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258261	WELL	PR	02/01/2001	GW	067-08344	MCMAHAN 2	PR

General Comment:

[Complaint inspection in response to noise complaint \(200440584\), low frequency sound survey at complainant residence per Rule 802.d](#)

Inspected Facilities

Facility ID: 258261 Type: WELL API Number: 067-08344 Status: PR Insp. Status: PR

Complaint

Comment: SW Inspection Supervisor conducted a low frequency (c-scale) sound survey at complainant residence with 3M Soundpro DL sound meter (serial no. BGN010014 factory calibrated 6.6.16) with a calibrated calibrator used for pre and post calibrations. 3 surveys were run between 6:40 and 8:20 AM (a time that complainant stated noise was most noticeable). Conditions were overcast, calm winds with temperatures between 20 and 30 deg F. Ambient noise sources include vehicle traffic on nearby US 550 and aircraft around La Plata County/Animas Air Park airports. Averaged noise levels were consistantly 59 or 60 db(c) 25' from the northwest or northeast corner of the residence in direction of equipment with soundmeter set on tripod 4' above ground level. Data report available via link on "attachement" page.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685200238	meter placement on NE corner of house towards wel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4028877
685200239	meter display at end of survey showing 59 db(c)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4028878
685200240	sound survey data report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4028879