

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2016

Submitted Date:

12/16/2016

Document Number:

666802822**FIELD INSPECTION FORM**

Loc ID 335853	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: <u>24</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290199	WELL	PR	01/04/2008	GW	045-14034	CLOUGH RWF 22-14	PR
290201	WELL	PR	02/28/2009	GW	045-14033	CLOUGH RWF 311-14	PR
290204	WELL	PR	04/11/2009	GW	045-14032	CLOUGH RWF 511-14	PR
290206	WELL	PR	09/30/2008	GW	045-14031	CLOUGH RWF 412-14	PR
290207	WELL	PR	02/28/2009	GW	045-14030	CLOUGH RWF 312-14	PR
290208	WELL	PR	09/30/2008	GW	045-14029	CLOUGH RWF 21-14	PR
290209	WELL	PR	10/19/2008	GW	045-14028	CLOUGH RWF 321-14	PR
290210	WELL	PR	09/30/2008	GW	045-14027	CLOUGH RWF 522-14	PR
290211	WELL	PR	01/04/2008	GW	045-14026	CLOUGH RWF 11-14	PR
290212	WELL	PR	10/06/2008	GW	045-14025	CLOUGH RWF 422-14	PR
290213	WELL	PR	01/04/2008	GW	045-14024	CLOUGH RWF 411-14	PR
290214	WELL	PR	10/23/2008	GW	045-14023	CLOUGH RWF 512-14	PR
290215	WELL	PR	01/04/2008	GW	045-14022	CLOUGH RWF 521-14	PR
290216	WELL	PR	05/20/2009	GW	045-14021	CLOUGH RWF 12-14	PR
290217	WELL	PR	03/31/2009	GW	045-14020	CLOUGH RWF 322-14	PR
290218	WELL	PR	06/30/2009	GW	045-14019	CLOUGH RWF 421-14	PR
420430	WELL	PR	10/01/2011	GW	045-20146	Clough RWF 313-14	PR
420432	WELL	PR	12/08/2011	GW	045-20147	Clough RWF 13-14	PR
420434	WELL	PR	12/08/2011	GW	045-20148	Clough RWF 323-14	PR
420437	WELL	PR	12/08/2011	GW	045-20149	Clough RWF 413-14	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	AIRS ID 045-1907-001		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		39.526974,-107.856347	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	290199	Type:	WELL	API Number:	045-14034	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290201	Type:	WELL	API Number:	045-14033	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290204	Type:	WELL	API Number:	045-14032	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290206	Type:	WELL	API Number:	045-14031	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290207	Type:	WELL	API Number:	045-14030	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290208	Type:	WELL	API Number:	045-14029	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290209	Type:	WELL	API Number:	045-14028	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290210	Type:	WELL	API Number:	045-14027	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	290211	Type:	WELL	API Number:	045-14026	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290212	Type:	WELL	API Number:	045-14025	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290213	Type:	WELL	API Number:	045-14024	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290214	Type:	WELL	API Number:	045-14023	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290215	Type:	WELL	API Number:	045-14022	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290216	Type:	WELL	API Number:	045-14021	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290217	Type:	WELL	API Number:	045-14020	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290218	Type:	WELL	API Number:	045-14019	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	420430	Type:	WELL	API Number:	045-20146	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	420432	Type:	WELL	API Number:	045-20147	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	420434	Type:	WELL	API Number:	045-20148	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	420437	Type:	WELL	API Number:	045-20149	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Retention Ponds	Pass			
		Ditches	Pass			
Sediment Traps	Pass					
Seeding	Pass					
Rip Rap	Pass					
Drains	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	424958	123456	
	424958	1642050	
	424958	1642050	