

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/15/2016
Submitted Date:
12/15/2016
Document Number:
673403938

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312926 _____ Waldron, Emily _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 95960
Name of Operator: WEXPRO COMPANY
Address: P O BOX 45003
City: SALT LAKE CITY State: UT Zip: 84145-

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fredrickson, Tammy	307-352-7566	Tammy.Fredrickson@questar.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222868	WELL	PR	04/29/2004	GW	081-06228	MUSSER, B W 20	PR

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	1-800-341-3129		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		40.948770,-108.331330
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	HEATED STEEL AST		40.948620,-108.331310
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 222868 Type: WELL API Number: 081-06228 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT