

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/15/2016

Submitted Date:

12/16/2016

Document Number:

675203689**FIELD INSPECTION FORM**

Loc ID 334732 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283573	WELL	PR	04/15/2007	GW	045-11944	ENCANA PAYTON 20-1 (PD21)	PR
283574	WELL	PR	06/22/2006	GW	045-11945	ENCANA PAYTON 20-1BB (PD21)	PR
283575	WELL	PR	04/12/2007	GW	045-11946	ENCANA 21-4BB(PD21)	PR
283576	WELL	PR	04/19/2007	GW	045-11947	ENCANA 21-4 (PD21)	PR
283582	WELL	PR	04/21/2007	GW	045-11949	ENCANA 21-3 (PD21)	PR
283585	WELL	PR	04/10/2007	GW	045-11948	ENCANA 21-5BB (PD21)	PR
283590	WELL	PR	02/01/2011	GW	045-11950	ENCANA MAHAFFEY 16-13 (PD21)	PR
288928	WELL	PR	04/07/2007	GW	045-13623	ENCANA FEDERAL 16-14BB (PD21)	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: <u>283573</u>	Type: <u>WELL</u>	API Number: <u>045-11944</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283574</u>	Type: <u>WELL</u>	API Number: <u>045-11945</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283575</u>	Type: <u>WELL</u>	API Number: <u>045-11946</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283576</u>	Type: <u>WELL</u>	API Number: <u>045-11947</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283582</u>	Type: <u>WELL</u>	API Number: <u>045-11949</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283585</u>	Type: <u>WELL</u>	API Number: <u>045-11948</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283590</u>	Type: <u>WELL</u>	API Number: <u>045-11950</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>288928</u>	Type: <u>WELL</u>	API Number: <u>045-13623</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT