

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2016

Submitted Date:

12/16/2016

Document Number:

675203690**FIELD INSPECTION FORM**

Loc ID 334750 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283783	WELL	PR	11/14/2007	GW	045-12001	ENCANA 21-6BB(PF21)	PR
283785	WELL	PR	07/03/2006	GW	045-12000	ENCANA 21-6 (PF21)	PR
283787	WELL	PR	03/01/2012	GW	045-11999	ENCANA 21-5 (PF21)	PR
283790	WELL	PR	11/14/2007	GW	045-11998	ENCANA 21-3BB(PF21)	PR
288991	WELL	PR	06/23/2007	GW	045-13627	ENCANA FEDERAL 21-2 (PF 21)	PR
288992	WELL	PR	11/14/2007	GW	045-13626	ENCANA FEDERAL 21-7BB (PF21)	PR
288993	WELL	PR	06/23/2007	GW	045-13625	ENCANA FEDERAL 21-7 (PF21)	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: <u>283783</u>	Type: <u>WELL</u>	API Number: <u>045-12001</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283785</u>	Type: <u>WELL</u>	API Number: <u>045-12000</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283787</u>	Type: <u>WELL</u>	API Number: <u>045-11999</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283790</u>	Type: <u>WELL</u>	API Number: <u>045-11998</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>288991</u>	Type: <u>WELL</u>	API Number: <u>045-13627</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>288992</u>	Type: <u>WELL</u>	API Number: <u>045-13626</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>288993</u>	Type: <u>WELL</u>	API Number: <u>045-13625</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT