

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2016

Submitted Date:

12/16/2016

Document Number:

675203696**FIELD INSPECTION FORM**

Loc ID 311692	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
------------------	------------------------------------	---	-------------------	--

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290492	WELL	PR	01/01/2013	GW	045-14125	GARDNER FEDERAL 21-15(PC28)	PR
290493	WELL	PR	01/29/2013	GW	045-14124	GARDNER 21-13(PC28)	PR
426547	WELL	PR	10/16/2012	GW	045-21184	Gardner Federal 28-1C (PC-28)	PR
426550	WELL	PR	12/06/2012	GW	045-21185	Gardner Federal 28-2A (PC-28)	PR
426551	WELL	PR	02/20/2013	GW	045-21186	Gardner Federal 28-2B (PC-28)	PR
426552	WELL	PR	02/20/2013	GW	045-21187	Gardner 28-4A (PC-28)	PR
426562	WELL	PR	10/09/2012	GW	045-21189	Gardner 21-14C (PC-28)	PR
426563	WELL	PR	10/08/2012	GW	045-21190	Gardner Federal 28-1 (PC-28)	PR
426564	WELL	PR	12/06/2012	GW	045-21191	Gardner 21-14 (PC-28)	PR
426565	WELL	PR	12/09/2012	GW	045-21192	Gardner Federal 28-2D (PC-28)	PR
426623	WELL	PR	12/06/2012	GW	045-21193	Gardner 28-3B (PC-28)	PR
429141	WELL	PR	12/20/2012	GW	045-21498	Gardner 28-3DD (PC-28)	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: <u>290492</u>	Type: <u>WELL</u>	API Number: <u>045-14125</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>290493</u>	Type: <u>WELL</u>	API Number: <u>045-14124</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426547</u>	Type: <u>WELL</u>	API Number: <u>045-21184</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426550</u>	Type: <u>WELL</u>	API Number: <u>045-21185</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426551</u>	Type: <u>WELL</u>	API Number: <u>045-21186</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426552</u>	Type: <u>WELL</u>	API Number: <u>045-21187</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426562</u>	Type: <u>WELL</u>	API Number: <u>045-21189</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426563</u>	Type: <u>WELL</u>	API Number: <u>045-21190</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426564</u>	Type: <u>WELL</u>	API Number: <u>045-21191</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426565</u>	Type: <u>WELL</u>	API Number: <u>045-21192</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426623</u>	Type: <u>WELL</u>	API Number: <u>045-21193</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>429141</u>	Type: <u>WELL</u>	API Number: <u>045-21498</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Gravel	Pass					
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT