

Reclamation Inspection

12/15/2016

Operator: Vista Operating Inc. #100128

Location ID: 317418

Washington County, CO

SENW Section 31 T2S R50W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo of GPS confirming location.



Figure 2: Photo taken from the location, facing north. Photo shows reclamation work appears to have been conducted.



Figure 3: Photo taken from the location. Photo shows straw used as mulch. Mulch appears to be over applied and areas and may hinder germination/reclamation.



Figure 4: Photo taken from the location. Photo shows straw used as mulch. Mulch appears to be over applied and areas and may hinder germination/reclamation.



Figure 5: Photo taken from the location, facing south. Photo shows reclamation work appears to have been conducted.