Inspector Name: MONTOYA, JOHN

**FORM INSP** Rev

X/15

**State of Colorado** Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



HSR ANNE STATE 9-7

Inspection Date: 12/12/2016

Submitted Date: 12/12/2016

**Document Number:** 685501628

SI

## FIELD INSPECTION FORM

11/01/2014

GW

PR

Loc ID	Inspector Na	me:	On-Site	Inspection			Status	Summary:	
329904	MONTOYA,	JOHN	2/	A Doc Num:			TH	IIS IS A FOLLOW UP INSPECT	ION
Operator In	nformation:						FC FC	LLOW UP INSPECTION REQU	JIRED
OGCC Ope	erator Number:	10548					X NO	FOLLOW UP INSPECTION R	EQUIRED
Name of Op	perator: HRM RES	SOURCES I	I LLC				Findin	<u>gs:</u>	
Address: 4	10 17TH STREE	Γ #1600					4 0	Number of Comments  Number of Corrective Actions	
City:	DENVER	State:	СО	Zip:	8020	2		rrective Action Response Requested	
Contact Inf	ormation:						-		
Contact Na	ame	Phone	е	Email			(	Comment	
Pape, Terr	у	303-8	93-6621	tpape@h	rmres	.com	,	All Inspections	
OLSON, J	USTIN	030-9	10-4717	justin.ols	on@h	mres.com	1 (	engineering	
Inspected I	Facilities:								
Facility ID	Туре	Status	Status Date	Well C	lass	API Num	)	Facility Name	Insp Status

123-18019

	_	
Canaral	Cammanti	
General	Comment:	

250216

WELL

Inspector Name: MONTOYA, JOHN

			Lo	ation			
Lease Road:							
Туре	Main						
comment:							
Corrective ActionL					Date	:	
Overall Good: X					I I		
Signs/Marker:							
	WELLHEAD						
Comment:							
Corrective Action:					Date	ə:	
Emergency Contact N	Jumber						
Comment:							
Corrective Action:					Date	 Date:	
Overall Good: 🔀			,				
<u>Spills:</u>							
Туре	Area	Volume					
In Containment: 1	No						
Comment:							
Multilple Spills	and Releases?						
Fencing/:							
	WELLHEAD						
	1 1/2" PIPE FENCE						
	SE CORNER N40.14290						
Corrective Action:				Date	e:		
Equipment:						corrective date	
Гуре: Plunger Lift		# 1					
Comment							
Corrective Action					Date:		
Venting:	1				l I		
Yes/No	NO						
Comment:							
Corrective Action:					Date:		
Flaring:					Date.		
CIALIDICI							
Туре							
					Date:		

Inspector Name: MONTOYA, JOHN

	,							
			Inspected	d Facilities				
Facility ID: 250216	Type:	WELL	API Number:	123-18019	Status: _	PR	Insp. Status:	SI
			<u>Idle V</u>	<u>Vell</u>				
Purpose: 🔀 Shut	In 🔲	Temporarily A	bandoned	Reminder:				
Comment:								
Corrective Action:							Date:	

## **Attached Documents**

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
685501628	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025237

Date Run: 12/19/2016 Doc [#685501628]