

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2016

Submitted Date:

12/19/2016

Document Number:

674703466**FIELD INSPECTION FORM**

Loc ID 335200	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL &amp; GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>				<b>Findings:</b> 21 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	<a href="#">EnCana Inspection email</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252	WELL	PR	03/27/2009	GW	045-15460	N. PARACHUTE MF02B C28 696	PR
253	WELL	PR	04/17/2009	GW	045-15461	N. PARACHUTE MF01A C28 696	PR
254	WELL	PR	04/17/2009	GW	045-15462	N. PARACHUTE MF01D C28 696	PR
255	WELL	PR	04/30/2009	GW	045-15463	N. PARACHUTE MF01C C28 696	PR
256	WELL	PR	03/31/2009	GW	045-15464	N. PARACHUTE MF02A C28 696	PR
258	WELL	PR	01/31/2009	GW	045-15465	N. PARACHUTE MF02D C28 696	PR
259	WELL	PR	04/14/2009	GW	045-15466	N. PARACHUTE MF01B C28 696	PR
260	WELL	PR	01/20/2009	GW	045-15467	N. PARACHUTE MF02C C28 696	PR
291912	WELL	PR	04/14/2009	GW	045-14553	N. PARACHUTE MF15A-21 C28 69	PR
291915	WELL	PR	01/19/2009	GW	045-14552	N. PARACHUTE MF10A-21C28 696	PR
291916	WELL	PR	04/15/2009	GW	045-14551	N. PARACHUTE MF10B-21C28 696	PR
291918	WELL	PR	04/17/2009	GW	045-14550	N. PARACHUTE MF10C-21 C28 69	PR
291920	WELL	PR	04/30/2009	GW	045-14549	N. PARACHUTE MF10D-21 C28 69	PR
292039	WELL	PR	04/14/2009	GW	045-14554	N. PARACHUTE MF15B-21C28696	PR
293694	WELL	PR	04/17/2009	GW	045-15108	N. PARACHUTE MF15C-21 C28 69	PR
293695	WELL	PR	04/17/2009	GW	045-15109	N. PARACHUTE MF16C-21 C28 69	PR

**General Comment:**

--

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date:

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 16		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical containment		
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:	Sells		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	<100 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)	80 bbl					
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities						
Facility ID:	252	Type:	WELL	API Number: 045-15460	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	253	Type:	WELL	API Number: 045-15461	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	254	Type:	WELL	API Number: 045-15462	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	255	Type:	WELL	API Number: 045-15463	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	256	Type:	WELL	API Number: 045-15464	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	258	Type:	WELL	API Number: 045-15465	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	259	Type:	WELL	API Number: 045-15466	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	260	Type:	WELL	API Number: 045-15467	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:

Facility ID: 291912	Type: WELL	API Number: 045-14553	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291915	Type: WELL	API Number: 045-14552	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291916	Type: WELL	API Number: 045-14551	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291918	Type: WELL	API Number: 045-14550	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291920	Type: WELL	API Number: 045-14549	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 292039	Type: WELL	API Number: 045-14554	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 293694	Type: WELL	API Number: 045-15108	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 293695	Type: WELL	API Number: 045-15109	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

--

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_



1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Compaction	Pass					
		Culverts	Pass			
				Material Handling And Spill Prevention	Pass	
		Compaction	Pass			
Slope Roughening	Pass					
Seeding	Pass					
Check Dams	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**    ☒ NO SURFACE INDICATION OF PIT