



Photo#1: View of Location from Entry Road to South.



Photo#2: Rip Rap Drain

Inspection Photos: Laramie Energy Cascade Creek Loc#423240


November 14, 2016



Emerged Vegetation.

Photo#3:

Photo #4



November 14, 2016

Inspection Photos: Laramie Energy Cascade  
Creek Loc#423240



Scattered Knap Weed in a few areas.  
Photo#5:



Photo:6:



November 14, 2016

Inspection Photos: Laramie Energy Cascade  
Creek Loc#423240





Photo#7: Land owner has parked Trailers at West Side of Location..

Inspection Photos: Laramie Energy Cascade Creek Loc#423240

November 14, 2016