

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2016

Submitted Date:

12/14/2016

Document Number:

675203670**FIELD INSPECTION FORM**

Loc ID 334569	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Terra, Energy		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257876	WELL	PR	01/05/2007	OW	045-07609	KNIGHT PA 41-4	PR
285148	WELL	PR	06/14/2006	GW	045-12381	KNIGHT PA 332-4	PR
285754	WELL	PR	07/19/2006	GW	045-12554	KNIGHT PA 42-4	PR
285755	WELL	PR	07/19/2006	GW	045-12548	KNIGHT PA 531-4	PR
285756	WELL	PR	07/19/2006	GW	045-12549	KNIGHT PA 341-4	PR
285758	WELL	PR	07/19/2006	GW	045-12547	KNIGHT PA 441-4	PR
285760	WELL	PR	07/19/2006	GW	045-12546	KNIGHT PA 431-4	PR
285762	WELL	PR	07/19/2006	GW	045-12545	KNIGHT PA 32-4	PR
285764	WELL	PR	07/19/2006	GW	045-12550	KNIGHT PA 432-4	PR
285766	WELL	PR	04/11/2007	GW	045-12551	KNIGHT PA 532-4	PR
285768	WELL	PR	07/19/2006	GW	045-12552	KNIGHT PA 342-4	PR
285771	WELL	PR	04/11/2007	GW	045-12553	KNIGHT PA 442-4	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type SEPARATOR

Comment:

Corrective Action:

Date:

Type WELLHEAD

Comment:

Corrective Action:

Date:

Type TANK BATTERY

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLS	STEEL AST		,	
Comment:						

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	<u>257876</u>	Type:	<u>WELL</u>	API Number:	<u>045-07609</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285148</u>	Type:	<u>WELL</u>	API Number:	<u>045-12381</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285754</u>	Type:	<u>WELL</u>	API Number:	<u>045-12554</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285755</u>	Type:	<u>WELL</u>	API Number:	<u>045-12548</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285756</u>	Type:	<u>WELL</u>	API Number:	<u>045-12549</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285758</u>	Type:	<u>WELL</u>	API Number:	<u>045-12547</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285760</u>	Type:	<u>WELL</u>	API Number:	<u>045-12546</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285762</u>	Type:	<u>WELL</u>	API Number:	<u>045-12545</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285764</u>	Type:	<u>WELL</u>	API Number:	<u>045-12550</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285766</u>	Type:	<u>WELL</u>	API Number:	<u>045-12551</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285768</u>	Type:	<u>WELL</u>	API Number:	<u>045-12552</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>285771</u>	Type:	<u>WELL</u>	API Number:	<u>045-12553</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Ditches	Pass	Compaction	Pass			
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203670	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4026946