

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2016

Submitted Date:

12/14/2016

Document Number:

675203681**FIELD INSPECTION FORM**
 Loc ID 334626 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Terra, Energy		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258716	WELL	PR	12/12/2000	GW	045-07650	KNIGHT PA 41-5	PR
280663	WELL	PR	10/17/2005	GW	045-11315	KNIGHT PA 512-4	PR
280716	WELL	PR	07/20/2006	GW	045-11325	KNIGHT PA 441-5	PR
280717	WELL	PR	10/18/2005	GW	045-11326	KNIGHT PA 641-5	PR
280719	WELL	PR	07/20/2006	GW	045-11327	KNIGHT PA 511-4	PR
280720	WELL	PR	07/20/2006	GW	045-11328	KNIGHT PA 12-4	PR
280721	WELL	PR	03/08/2007	GW	045-11329	KNIGHT PA 312-4	PR
280722	WELL	PR	07/20/2006	GW	045-11330	KNIGHT PA 341-5	PR
280723	WELL	PR	07/20/2006	GW	045-11331	KNIGHT PA 411-4	PR
280724	WELL	PR	07/20/2006	GW	045-11332	KNIGHT PA 412-4	PR
280725	WELL	PR	10/18/2005	GW	045-11333	KNIGHT PA 541-5	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities				
Facility ID:	<u>258716</u>	Type:	<u>WELL</u>	API Number: <u>045-07650</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>280663</u>	Type:	<u>WELL</u>	API Number: <u>045-11315</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>280716</u>	Type:	<u>WELL</u>	API Number: <u>045-11325</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>280717</u>	Type:	<u>WELL</u>	API Number: <u>045-11326</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>280719</u>	Type:	<u>WELL</u>	API Number: <u>045-11327</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>280720</u>	Type:	<u>WELL</u>	API Number: <u>045-11328</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>280721</u>	Type:	<u>WELL</u>	API Number: <u>045-11329</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>280722</u>	Type:	<u>WELL</u>	API Number: <u>045-11330</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>280723</u>	Type:	<u>WELL</u>	API Number: <u>045-11331</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>280724</u>	Type:	<u>WELL</u>	API Number: <u>045-11332</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>280725</u>	Type:	<u>WELL</u>	API Number: <u>045-11333</u> Status: <u>PR</u> Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
		Gravel	Pass			
Gravel	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203681	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033384