



Photo#1: View of Location from Entry Road to East.



Photo#2: Guy Anchor; Mark or remove.

Inspection Photos: URSA Dever Loc#311676

December 14, 2016



Weeds have become Debris and tumbled into Well Area & Cellars.

Photo#3:

Photo #4



December 14, 2016

Inspection Photos: URSA Dever Loc#311676