

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2016

Submitted Date:

12/21/2016

Document Number:

674703475**FIELD INSPECTION FORM**

Loc ID 335651	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>				Findings: 15 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282285	WELL	PR	11/15/2012	GW	045-11725	N PARACHUTE WF09C-25I25A596	PR
292025	WELL	PR	11/15/2012	GW	045-14573	N PARACHUTE WF10B-25I25A596	PR
292026	WELL	PR	11/15/2012	GW	045-14572	N PARACHUTE WF10C-25I25A596	PR
292027	WELL	PR	11/15/2012	GW	045-14571	N PARACHUTE WF09A-25I25A596	PR
292028	WELL	PR	08/27/2007	GW	045-14570	N PARACHUTE WF16A-25I25A596	PR
292029	WELL	PR	08/31/2008	GW	045-14569	N PARACHUTE WF09D-25I25A596	PR
292030	WELL	PR	11/15/2012	GW	045-14568	N PARACHUTE WF09B-25I25A596	PR
292031	WELL	PR	11/15/2012	GW	045-14567	N PARACHUTE WF10A-25I25A596	PR
292032	WELL	PR	11/15/2012	GW	045-14566	N PARACHUTE WF10D-25I25A596	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Snow packed		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical containers		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 9		
Comment:	Gas lift meters		
Corrective Action:		Date:	
Type: Plunger Lift	# 9		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	282285	Type:	WELL	API Number:	045-11725	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	292025	Type:	WELL	API Number:	045-14573	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	292026	Type:	WELL	API Number:	045-14572	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	292027	Type:	WELL	API Number:	045-14571	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	292028	Type:	WELL	API Number:	045-14570	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	292029	Type:	WELL	API Number:	045-14569	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	292030	Type:	WELL	API Number:	045-14568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	292031	Type:	WELL	API Number:	045-14567	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	

Comment: Limited inspection due to snow cover

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT