

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2016

Submitted Date:

12/21/2016

Document Number:

674703477**FIELD INSPECTION FORM**

Loc ID 335848	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED							
2A Doc Num: _____			Findings: 23 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested							
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>										
Contact Information:										
<table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Inspections, General</td> <td>970-285-2665</td> <td>cogcc.inspections@encana.com</td> <td>EnCana Inspection email</td> </tr> </table>				Contact Name	Phone	Email	Comment	Inspections, General	970-285-2665	cogcc.inspections@encana.com
Contact Name	Phone	Email	Comment							
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email							

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283784	WELL	PR	05/03/2007	GW	045-12002	N. PARACHUTE WF06B A36 596	PR
283788	WELL	PR	01/14/2007	GW	045-12004	N.PARACHUTE WF07B A36 596	PR
283789	WELL	PR	03/15/2006	GW	045-12005	N. PARACHUTE WF06D A36 596	PR
283791	WELL	PR	02/01/2011	GW	045-12006	N.PARACHUTE WF07D A36 596	PR
283796	WELL	PR	03/12/2007	GW	045-11997	N. PARACHUTE WF03D A36 596	PR
283798	WELL	PR	03/12/2007	GW	045-11996	N. PARACHUTE WF04D A36 596	PR
283800	WELL	PR	02/01/2014	GW	045-11995	N. PARACHUTE WF02B A36 596	PR
289595	WELL	PR	03/06/2007	GW	045-13804	N. PARACHUTE WF02D-DX A36 59	PR
294899	WELL	PR	03/10/2008	GW	045-15628	N. PARACHUTE WF15C-25 A36 59	PR
294900	WELL	PR	11/02/2008	GW	045-15629	N. PARACHUTE WF15A-25 A36 59	PR
294901	WELL	PR	10/13/2008	GW	045-15630	N. PARACHUTE WF07C-36 A36 59	PR
294902	WELL	PR	10/26/2008	GW	045-15631	N. PARACHUTE WF07A-36 A36 59	PR
294903	WELL	PR	10/13/2008	GW	045-15632	N. PARACHUTE WF06A-36 A36 59	PR
294909	WELL	PR	10/25/2008	GW	045-15633	N. PARACHUTE WF03C-36 A36 59	PR
294910	WELL	PR	10/25/2008	GW	045-15634	N. PARACHUTE WF02A-36 A36 59	PR
294912	WELL	PR	10/13/2008	GW	045-15636	N. PARACHUTE WF06C-36 A36 59	PR

294913	WELL	PR	10/23/2008	GW	045-15635	N. PARACHUTE WF02C-36 A36 69	PR
--------	------	----	------------	----	-----------	---------------------------------	----

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Snow packed		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 17		
Comment:	Sells		
Corrective Action:		Date:	
Type: Plunger Lift	# 17		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 17		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		

Comment:	Chemical containers		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	283784	Type:	WELL	API Number:	045-12002	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	283788	Type:	WELL	API Number:	045-12004	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	283789	Type:	WELL	API Number:	045-12005	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	283791	Type:	WELL	API Number:	045-12006	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	283796	Type:	WELL	API Number:	045-11997	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	283798	Type:	WELL	API Number:	045-11996	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	283800	Type:	WELL	API Number:	045-11995	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	289595	Type:	WELL	API Number:	045-13804	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 294899	Type: WELL	API Number: 045-15628	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 294900	Type: WELL	API Number: 045-15629	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 294901	Type: WELL	API Number: 045-15630	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 294902	Type: WELL	API Number: 045-15631	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 294903	Type: WELL	API Number: 045-15632	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 294909	Type: WELL	API Number: 045-15633	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 294910	Type: WELL	API Number: 045-15634	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 294912	Type: WELL	API Number: 045-15636	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Seeding	Pass					
Berms						
				Material Handling And Spill Prevention	Pass	
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	287277	1433524	
	287277	1433524	