

# Reclamation Inspection

12/21/2016

Operator: Atlas Resources #200149

Location ID: 424293

Phillips County, CO

SWSE Section 27 T9N R43W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



**Figure 1:** Photo of GPS verifying location.



**Figure 2:** Photo taken from the northwest end of the location, facing south. Photo shows the vegetation over the interim area.



**Figure 3:** Photo taken from the northwest end of the location, facing east. Photo shows the vegetation over the interim area.



**Figure 4:** Photo taken from the southwest end of the location, facing north. Photo shows the vegetation over the interim area.



**Figure 5:** Photo taken from the southwest end of the location, facing east. Photo shows the vegetation over the interim area.



**Figure 6:** Photo taken from the southeast end of the location, facing west. Photo shows the vegetation over the interim area.



**Figure 7:** Photo taken from the southeast end of the location, facing north. Photo shows the vegetation over the interim area.



**Figure 8:** Photo taken from the northeast end of the location, facing south. Photo shows the vegetation over the interim area.



**Figure 9:** Photo taken from the northeast end of the location, facing west. Photo shows the vegetation over the interim area.