

Reclamation Inspection

12/21/2016

Operator: Atlas Resources #200149

Location ID: 314064

Phillips County, CO

SESE Section 27 T9N R43W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Search Bar	Searching for	My Current Location
Enter Search		
09506155	07'	SE
09506321	0.27'	W
09506395	0.27'	S
09506322	0.37'	NW

GARMIN

Figure 1: Photo of GPS verifying location.



Figure 2: Photo taken from the southwest end of the location, facing east. Photo shows the vegetation over the interim area.



Figure 3: Photo taken from the southwest end of the location, facing north. Photo shows the vegetation over the interim area.



Figure 4: Photo taken from the southeast end of the location, facing west. Photo shows the vegetation over the interim area.



Figure 5: Photo taken from the southeast end of the location, facing north. Photo shows the vegetation over the interim area.



Figure 6: Photo taken from the northeast end of the location, facing south. Photo shows the vegetation over the interim area.



Figure 7: Photo taken from the northeast end of the location, facing west. Photo shows the vegetation over the interim area.



Figure 8: Photo taken from the northwest end of the location, facing south. Photo shows the vegetation over the interim area.



Figure 9: Photo taken from the northwest end of the location, facing east. Photo shows the vegetation over the interim area.