

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2016

Submitted Date:

12/22/2016

Document Number:

682501546**FIELD INSPECTION FORM**
 Loc ID 426987 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 200149Name of Operator: ATLAS RESOURCES LLC DBA ATLAS ROCKIES LLCAddress: 3500 MASSILLON ROAD #100City: UNIONTOWN State: OH Zip: 44685**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lueth, Brock		blueth@enerjexresources.com	All Inspections
Aldstadt, Janice		jaldstadt@blackravenenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426999	WELL	PR	05/01/2015	GW	095-06401	VIESELMAYER 943-33-33	RI

General Comment:

This is an interim reclamation and stormwater inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

OTHER

Comment:

Rule 604.c(2)N requires "materials that might constitute a fire hazard shall be removed a minimum of twenty-five (25) feet from the wellhead"... Surface owner appears to be planting crop within twenty-five (25) feet of the wellhead. Inspector advises that operator's name discuss these concerns with the surface owner, to mitigate future conflicts with COGCC rules.

Corrective Action: Date: Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Inspected Facilities									
Facility ID:	426999	Type:	WELL	API Number:	095-06401	Status:	PR	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____ Pass _____

Comment [No waste or debris found on location or reclamation area.](#)

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____ Pass _____

Comment [No unused/unneeded equipment/materials found being stored on location or reclamation area.](#)

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment [N/A](#)

Corrective Action _____

Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? P

Comment

This location meets reclamation regulations; sufficient uniform vegetative cover. Areas of the location not needed for production, or are no longer in use have been reduced and reclaimed. Cropland has achieved uniform distribution and is indistinguishable from the adjacent reference areas.

Corrective Action

Date _____

Overall Interim Reclamation Pass**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Inspector Name: Trujillo, Aaron

Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>
---------------------------------	--	--

COGCC Comments

Comment	User	Date
2A Doc. #400226661 states size of location post interim reclamation to be 1 acre. Location appears to be <1 acre in size.	trujilloam	12/22/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682501547	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4035806