

Reclamation Inspection

12/20/2016

Operator: Atlas Resources #200149

Location ID: 314158

Phillips County, CO

NENE Section 5 T8N R43W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 2: Photo taken from the northeast corner of the location, facing south. Photo shows vegetation over the reclamation area.



Figure 3: Photo taken from the northeast corner of the location, facing west. Photo shows vegetation over the reclamation area.



Figure 4: Photo taken from the northwest corner of the location, facing east. Photo shows vegetation over the reclamation area.



Figure 5: Photo taken from the northwest corner of the location, facing south. Photo shows vegetation over the reclamation area.



Figure 6: Photo taken from the southwest corner of the location, facing north. Photo shows vegetation over the reclamation area.



Figure 7: Photo taken from the southwest corner of the location, facing east. Photo shows vegetation over the reclamation area.



Figure 8: Photo taken from the southeast corner of the location, facing west. Photo shows vegetation over the reclamation area.



Figure 9: Photo taken from the southeast corner of the location, facing north. Photo shows vegetation over the reclamation area.