

Location			
Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Lease sign by main access road		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	
Equipment:			
Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Kubota gas engine		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 294752 Type: WELL API Number: 125-11148 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(HAYS 3-1, 3-6, 3-8, 3-10, 3-15, 31-03, 32-03, HAYS STATE 2-5\) 1850' SE @ 39.91219/-102.28465](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: EROSION ON ACCESS TO WELLHEAD. EROSION LEADING ONTO AND OFF OF LOCATION

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT