

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/23/2016

Submitted Date:

12/23/2016

Document Number:

680703491**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 307071 Peterson, Tom 2A Doc Num: _____

Operator Information:OGCC Operator Number: 95233Name of Operator: WELLINGTON OPERATING COMPANYAddress: 6065 S QUEBEC ST STE 200City: CENTENNIAL State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pomeroy, Bradley		pomoco@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216739	WELL	PR	04/01/2012	OW	069-05161	W F MUDDY UT-D. COOK 26-1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor on pumpjack		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		

Comment: N40.75710 W-105.04449		Date:
Corrective Action:		Date:
Type: Deadman # & Marked	# 8	
Comment:		Date:
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment: N40.75716 W-105.04442		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		40.757190,-105.044080
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		40.756870,-105.044110
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST		40.757190,-105.044080
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLS	STEEL AST		40.756870,-105.044110
Comment:					
Corrective Action:					
				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities				
Facility ID: 216739	Type: WELL	API Number: 069-05161	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:			Date:	

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT