



Photo#1: View to North of Access Road into Location.

December 22, 2016

Inspection Photos: Encana Parker Ranch API#045-06929



Photo#2: Overview from Location Center to South.

Photo#3:

Noxious Weed, Plumeless Thistle is scattered across Location.



Photo#4:





Photo#5:

Rock Stock Piles ; one on East & one on West side of Location.

Photo#6:



Photo#7:

Photo#8:

Wattles are in Place along NE Perimeter of Location





Photo#9: Grasses appear Well Established

Inspection Photos: Encana Parker Ranch API#045-06929

December 22, 2016