

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/28/2016

Submitted Date:

12/28/2016

Document Number:

685302050**FIELD INSPECTION FORM**
 Loc ID 334029 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 34725Name of Operator: GOSNEY & SONS INCAddress: P O BOX 367City: BAYFIELD State: CO Zip: 81122**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Barnett, Matt		mattb@gosneyco.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275602	WELL	PR	10/23/2006	GW	007-06208	CONLEY 6	PR
295721	WELL	PR	06/28/2010	GW	007-06251	CONLEY 6-A	PR
295728	WELL	PR	06/28/2010	GW	007-06250	CONLEY 6-B	PR

**General Comment:**

Inspection report contains comments. See Tanks and Berms Section of report for additional details.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Panel and concrete barriers.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas Meter Run - Concrete barriers.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel and concrete barriers		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Post and Wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Safety Rails		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Ancillary equipment	# 3				
Comment: <a href="#">Wellhead</a>					
Corrective Action:				Date:	
Type: Deadman # & Marked	# 10				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 3				
Comment:					
Corrective Action:				Date:	
Type: Other	# 1				
Comment: <a href="#">Domestic Gas Tap</a>					
Corrective Action:				Date:	
Type: Gas Meter Run	# 3				
Comment:					
Corrective Action:				Date:	
Type: Other	# 1				
Comment: <a href="#">Water can and Valve Set</a>					
Corrective Action:				Date:	
Type: Plunger Lift	# 2				
Comment:					
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Flow Line	# 3				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment: <a href="#">Telemetry Equipment</a>					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment: <a href="#">Natural Gas Motor</a>					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		,	

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Grass and weed growth inside containment berms needs to be treated to maintain berm and base permeability.			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 275602 Type: WELL API Number: 007-06208 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 295721 Type: WELL API Number: 007-06251 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 295728 Type: WELL API Number: 007-06250 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Location partially covered in snow. Landowner storage on the SE corner of location.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**    ☒ NO SURFACE INDICATION OF PIT



**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 37.004790 Long: -107.272890Wind: Calm Speed:        (mph) Direction From:        Weather: Clear Temperature: 32 (F)Assisting Staff:        Camera #:       ☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
10:40	AM	11:05	AM

Equipment
Separation Equipment
Wellhead(s)
Water Tank(s)

Comment: Nothing noted at time of inspection.Corrective  
Action:

Date: