

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/29/2016
Submitted Date:
12/29/2016
Document Number:
675203722

FIELD INSPECTION FORM

Loc ID 422328 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

1 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422297	WELL	PR	08/07/2012	GW	045-20544	Cook Exxon 17-16C (PB-20)	PR
422298	WELL	PR	09/13/2012	GW	045-20545	Cook Gardner 20-4A (PB-20)	PR
422299	WELL	PR	09/13/2012	GW	045-20546	Cook Exxon 20-5BB (PB-20)	PR
422307	WELL	PR	09/13/2012	GW	045-20551	Cook Martin 20-1C (PB-20)	PR
422311	WELL	PR	09/13/2012	GW	045-20554	Cook Gardner 20-4BB (PB-20)	PR
422315	WELL	PR	09/13/2012	GW	045-20557	Cook Carpenter 20-3C (PB-20)	PR
422316	WELL	PR	09/13/2012	GW	045-20558	Cook Carpenter 20-3A (PB-20)	PR
422318	WELL	PR	09/13/2012	GW	045-20559	Cook Martin 20-1D (PB-20)	PR
422321	WELL	PR	09/13/2012	GW	045-20561	Cook Gardner 20-4 (PB-20)	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Vertical Heated Separator	# 9		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 422297 Type: WELL API Number: 045-20544 Status: PR Insp. Status: PRFacility ID: 422298 Type: WELL API Number: 045-20545 Status: PR Insp. Status: PRFacility ID: 422299 Type: WELL API Number: 045-20546 Status: PR Insp. Status: PRFacility ID: 422307 Type: WELL API Number: 045-20551 Status: PR Insp. Status: PRFacility ID: 422311 Type: WELL API Number: 045-20554 Status: PR Insp. Status: PRFacility ID: 422315 Type: WELL API Number: 045-20557 Status: PR Insp. Status: PRFacility ID: 422316 Type: WELL API Number: 045-20558 Status: PR Insp. Status: PRFacility ID: 422318 Type: WELL API Number: 045-20559 Status: PR Insp. Status: PRFacility ID: 422321 Type: WELL API Number: 045-20561 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Berms	Pass					
Retention Ponds	Pass					
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT